

My laptop G570 Laptop not detecting USB

Posted by lenovoadmin - 06 Jan 2017 08:12

Hi did you tried connecting to a different PC? Doing this will confirm whether USB ports or USB itself is damaged!!! Chances are less if all ports are bad at same time. Just check and revert.

=====