Lenovo Service Center - Lenovo Service Centers Contacts

Generated: 1 July, 2025, 22:25

SD card defective in Lenovo T430 Posted by lenovoadmin - 06 Jan 2017 08:57

.....

It seems to be a very starightforward socket replacement. The socket is soldered to a replaceable board and the board is screwed to the housing. Sadly there is not an ifixit manual but I'm sure you can find something online.
